

ಸಮೃದ್ಧಿ

॥ ಶ್ರೀ ಗಂಗಮ್ಮ ಕೃಪಾ ॥

Smt. Kavitha Singh
Mob : 9964702826

Samrudhi Ground Water Consultant

46, Gangamma Temple Street, Near Gangamma Temple, Malleshwaram, Bangalore-03.

Ref. :

Date : 06/04/2017

REPORT ON GROUND WATER INVESTIGATION

Name ಶ್ರೀ.ಶ್ರೀ.ಸಿ.ಸಿ.

Address ಮುಖ್ಯ ರಸ್ತೆ 3

Chick Ballari

Location

Topography Flat land

Soil Type Heavy soil

Rock Type Hard rock

Nos. ①

RECOMMENDATIONS

Depth 800 - 1000

Casing 100 - 150

Yield 290, 650, 910

Aquifers 3

Remarks No for 1000 feet

Note : The Survey was carried out by this divining / Geophysical method of Surveying is with our good knowledge and experience, However no guarantee of water will be given

ನೀರು ಅತ್ಯಮೂಲ್ಯ, ಅದನ್ನು ಸಂರಕ್ಷಿಸಿ... Water is precious, Conserve it... ನೀಡ ಬೆಳೆಸಿ, ಮರಗಳನ್ನು ಉಳಿಸಿ

AE W.S.

Smt. Kavitha Singh

Water Diviner

ಶ್ರೀ

॥ ಶ್ರೀ ಗಂಗಮ್ಮ ಕೃಪಾ ॥

Smt. Kavitha Singh
Mob : 9964702826

Amrudhi Ground Water Consultant

46, Gangamma Temple Street, Near Gangamma Temple, Malleshwaram, Bangalore-03.

Date : 06/04/2017

Ref. :

REPORT ON GROUND WATER INVESTIGATION

Name

B. B. S. S.

Address

46/2 No

Malleshwaram

Location

Topography

Plain land

Soil Type

Granite soil

Rock Type

hard rock

RECOMMENDATIONS

Nos.

Depth

100 - 150

Casing

100 - 200

Yield

2101 4801 910

Aquifers

3

Remarks

Water is present

Note : The Survey was carried out by this divining / Geophysical method of Surveying is with our good knowledge and experience, However no guarantee of water will be given

ನೀರು ಅತ್ಯಮೂಲ್ಯ, ಅದನ್ನು ಸಂರಕ್ಷಿಸಿ... Water is precious, Conserve it... ನೀಡ ಬೆಳೆಸಿ, ಮರಗಳನ್ನು ಉಳಿಸಿ

AE W3

Smt. Kavitha Singh

Water Diviner

೨೨

॥ ಶ್ರೀ ಗಂಗಮ್ಮ ಕೃಪಾ ॥

Smt. Kavitha Singh
Mob : 9964702826

amrudhi Ground Water Consultant

46, Gangamma Temple Street, Near Gangamma Temple, Malleshwaram, Bangalore-03.

Ref. :

Date : 06/04/2017

REPORT ON GROUND WATER INVESTIGATION

Name ಶ್ರೀ.ಬಿ.ಎ.ಎ

Address ward No. 3

Location Kaveri Layout
Near Narayan School

Topography Plain landy

Soil Type Regent's clay

Rock Type hard rock

Nos. ①

RECOMMENDATIONS

Depth 800 - 1000

Casing 100 - 150

Yield 290, 100, 750

Aquifers 2'

Remarks Water is not available

Note : The Survey was carried out by this divining / Geophysical method of Surveying is with our good knowledge and experience, However no guarantee of water will be given

ನೀರು ಅತ್ಯಮೂಲ್ಯ, ಅದನ್ನು ಸಂರಕ್ಷಿಸಿ... Water is precious, Conserve it... ಗಿಡ ಬೆಳೆಸಿ, ಮರಗಳನ್ನು ಉಳಿಸಿ

Smt. Kavitha Singh

Water Diviner

AE W3
10/3

॥ ಶ್ರೀ ಗಂಗಮ್ಮ ಕೃಪಾ ॥

Smt. Kavitha Singh
Mob : 9964702826

೨೬

Amrudhi Ground Water Consultant

46, Gangamma Temple Street, Near Gangamma Temple, Malleshwaram, Bangalore-03.

Date 05/04/17

Ref. :

REPORT ON GROUND WATER INVESTIGATION

Name B. B. N. S.

Address Ward No 3

Gangamma Temple Road

Location

Topography Plain land

Soil Type Magadi Soil

Rock Type hard rock

Nos. ①

RECOMMENDATIONS

Depth 300 - 1000

Casing 180 to 220

Yield 110 to 190

Aquifers 2/1

Remarks Mineral water filter pipe. Not over

Note : The Survey was carried out by this divining / Geophysical method of Surveying is with our good knowledge and experience, However no guarantee of water will be given

ನೀರು ಅತ್ಯಮೂಲ್ಯ, ಅದನ್ನು ಸಂರಕ್ಷಿಸಿ... Water is precious, Conserve it... ನಿಡ ಬೆಳೆಸಿ, ಮರಗಳನ್ನು ಉಳಿಸಿ

Smt. Kavitha Singh

Water Diviner

ಕಮೃದ್ಧಿ

|| ಶ್ರೀ ಗಂಗಮ್ಮ ಕೃಪಾ ||

Smt. Kavitha Singhi
Mo. 9964702826

Samrudhi Ground Water Consultant

46, Gangamma Temple Street, Near Gangamma Temple, Malleswaram, Bangalare-03

Ref. :

Date : 27/04/2017

REPORT ON GROUND WATER INVESTIGATION

Name _____ BSRP

Address _____ ward-03

Location _____ East County-II

Topography _____

Soil Type _____ Black Cotton Soil

Rock Type _____ Hard

RECOMMENDATIONS

Nos.

Depth _____ 1050' _____ Depth _____ 1100'

Casing _____ 250' _____ Casing _____ 300'

Yield _____ 2" _____ Yield _____ 2 1/2"

Aquifers _____ Aquifers _____

Remarks _____ Loose soil pvc pipe laying

Note : The Survey was carried out by this diving / Geophysical method of Surveying is with our good knowledge and experience, However no guarantee of water will be given

ನೀರು ಅತ್ಯಮೂಲ್ಯ, ಅದನ್ನು ಸಂರಕ್ಷಿಸಿ... Water is precious, Conserve it... ಗಿಡ ಬೆಳೆಸಿ, ಮರಗಳನ್ನು ಉಳಿಸಿ

Smt. Kavitha Singh

ಮೃದ್ಧಿ

॥ ಶ್ರೀ ಗಂಗಮ್ಮ ಕೃಪಾ ॥

Smt. Kavitha Singh
Mob : 9964702826

Samrudhi Ground Water Consultant

46, Gangamma Temple Street, Near Gangamma Temple, Malleshwaram, Bangalore-03.

Ref. :

Date : 25/04/2017

REPORT ON GROUND WATER INVESTIGATION

Name ಶ್ರೀಂಪ

Address ಮಾಲೇಶ್ವರಂ-03

Location ಮಾಲೇಶ್ವರಂ ಹೈವೆ 2nd main / 2nd Cross

Topography

Soil Type Red Soil

Rock Type Smooth Rock

Nos. **RECOMMENDATIONS**

Depth 1000' - 1100'

Casing 200' - 250'

Yield 2 1/2"

Aquifers

Remarks Free pipe down

Note : The Survey was carried out by this divining / Geophysical method of Surveying is with our good knowledge and experience, However no guarantee of water will be given

ನೀರು ಅತ್ಯಮೂಲ್ಯ, ಅದನ್ನು ಸಂರಕ್ಷಿಸಿ... Water is precious, Conserve it... ನೀಡ ಬೆಳೆಸಿ, ಮರಗಳನ್ನು ಉಳಿಸಿ

AE W3

Smt. Kavitha Singh

[Signature]

Water Diviner

|| ಶ್ರೀ ಗಂಗಮ್ಮ ಕೃಪಾ ||

Smt. Kavitha Singh
Mo. 9964702826

ಸಮೃದ್ಧಿ

Samrudhi Ground Water Consultant

46, Gangamma Temple Street, Near Gangamma Temple, Malleswaram, Bangalore-03

Date : 27/04/2017

Ref. :

REPORT ON GROUND WATER INVESTIGATION

Name BBMP
Address ward-23
Location on shakti Temple Road
Topography
Soil Type Red Soil
Rock Type Hard Rck

RECOMMENDATIONS

Nos.

Depth	<u>1000'</u>	Depth	<u>1200'</u>
Casing	<u>200'</u>	Casing	<u>250'</u>
Yield	<u>2"</u>	Yield	<u>2 1/2"</u>
Aquifers		Aquifers	

Remarks Pvc pipe only

Note : The Survey was carried out by this divining / Geophysical method of Surveying is with our good knowledge and experience, However no guarantee of water will be given

ನೀರು ಅತ್ಯಮೂಲ್ಯ, ಅದನ್ನು ಸಂರಕ್ಷಿಸಿ... Water is precious, Conserve it... ನೀಡ ಬೆಲೆ, ಮರಗಳನ್ನು ಉಳಿಸಿ

Smt. Kavitha Singh

(Signature)



VINAYAKA ENTERPRISES

Borewell Drilling Contractors

Mobile : +91 9342202932 / 9343202932

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore 560094

Date : 25/04/2017

No. : **116**

1. Customer's Name and Address :
with Telephone No.

ISBmp
cond-03

2. Well Location :

Atturugundi

3. Total Well Depth / Drilled in Ft. :

900' - 1000'

4. Casing Erected in Ft. :

200' - 250'

5. Water Struck at the Depth of :

600'

6. Total Yield (Measuring method "V" Norch) : 2 1/2 / Inches on "V" Norch)

7. Formation of Soil/Well Water Condition : Boulders/Silt/Loose Soil/Clear Boulders

8. At the Depth of :

900'

9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good/satisfied / Party agreed conditions.

Once the well handed over to party, company is no way responsible for further developments if anything in the well or whatsoever.

Party's Signature

I, owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For **VINAYAKA ENTERPRISES**

AEW3

Party's Signature

N. S. S.
Manager / Proprietor

BOREWELL COMPLETION REPORT



VINAYAKA ENTERPRISES

Borewell Drilling Contractors

Mobile : +91 9342202932 / 9343202932

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore 560094

Date : 28/04/2017

No. : 116

1. Customer's Name and Address : BBS mp
with Telephone No. : 080-23
2. Well Location : ISLPS layout
3. Total Well Depth / Drilled in Ft. : 1000' - 1100'
4. Casing Erected in Ft. : 200' - 250'
5. Water Struck at the Depth of : 500'
6. Total Yield (Measuring method "V" Norch) : 2 1/2 / Inches on "V" Norch)
7. Formation of Soil/Well Water Condition : Boulders/Silt/Loose Soil/Clear hard soil
8. At the Depth of : 900'
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good/satisfied / Party agreed conditions.

Once the well handed over to party, company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I, owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

[Signature]

Manager / Proprietor

[Signature]

Party's Signature



VINAYAKA ENTERPRISES

Borewell Drilling Contractors

Mobile : +91 9342202932 / 9343202932

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore 560094

Date : 22/04/2017

No. : **116**

1. Customer's Name and Address :
with Telephone No.

BISMP
coor-d-03

2. Well Location :

Kaveri Layout (Narayana School)

3. Total Well Depth / Drilled in Ft. :

1000' - 1100'

4. Casing Erected in Ft. :

920' - 260'

5. Water Struck at the Depth of :

600'

6. Total Yield (Measuring method "V" Norch) :

2 1/2" / Inches on "V" Norch)

7. Formation of Soil/Well Water Condition : Boulders/Silt/Loose Soil/Clear

Loose Soil

8. At the Depth of :

980'

9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good/satisfied / Party agreed conditions.

Once the well handed over to party, company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I, owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For **VINAYAKA ENTERPRISES**

[Signature]

Manager / Proprietor

AE W3
[Signature]

Party's Signature

**BOREWELL
COMPLETION REPORT**

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

Mobile : +91 9342202932 / 9343202932

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore 560094

No. : **118**Date : 18/04/2017

1. Customer's Name and Address : BISMP
with Telephone No. ward-03
2. Well Location : Jelly mission Circle Road.
3. Total Well Depth / Drilled in Ft. : 1100' - 1200'
4. Casing Erected in Ft. : 300' - 720'
5. Water Struck at the Depth of : 800'
6. Total Yield (Measuring method "V" Norch : 2" / Inches on "V" Norch)
7. Formation of Soil/Well Water Condition : Boulders/Silt/Loose Soil/Clear Boulders
8. At the Depth of : 920'
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good/satisfied / Party agreed conditions.

Once the well handed over to party, company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I, owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

Party's Signature

For **VINAYAKA ENTERPRISES**

Manager / Proprietor



VINAYAKA ENTERPRISES

Borewell Drilling Contractors

**BOREWELL
COMPLETION REPORT**

Mobile : +91 9342202932 / 9343202932

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore 560094

No. : **116**

Date : 26/04/2017

1. Customer's Name and Address :
with Telephone No.

ISBAP
CO-OP NO-03

2. Well Location :

Ayyappa Layout (Inner Side Hanyakangaru)

3. Total Well Depth / Drilled in Ft. :

970' - 990'

4. Casing Erected in Ft. :

250' - 300'

5. Water Struck at the Depth of :

780'

6. Total Yield (Measuring method "V" Norch) : 2 1/2 / Inches on "V" Norch

7. Formation of Soil/Well Water Condition : Boulders/Silt/Loose Soil/Clear

Red Soil

8. At the Depth of :

980'

9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good/satisfied / Party agreed conditions.

Once the well handed over to party, company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I, owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

Party's Signature

For **VINAYAKA ENTERPRISES**

[Signature]

Manager / Proprietor

AEW3
20